



LEGEND

Drainage Issues

Sewer Issues

Pedestrian Issues

Driving Issues

Cycling Issues

Miscellaneous Issues

Fire Station

Playground

School

?

One Way Street Direction

71

Address

@

Catch Basin

02550100150200

Feet

GLOBAL ISSUES

- DRAINAGE ISSUES

COUPLE OF PROPERTIES HAVE STREET RUNOFF DRAIN TOWARDS BACKYARD.
- SEWER ISSUES

A COUPLE OF PROPERTIES WITH SEWER SERVICE ISSUES.
- PEDESTRIAN ISSUES

BOTH ENDS OF LAKEVIEW AVENUE HAVE UNEVEN SIDEWALKS.
- DRIVING ISSUES

SPEED IS A MAJOR CONCERN.

POTHOLES ARE EVERYWHERE.

DRIVERS OFTEN DRIVE THE WRONG WAY ON SECTION BETWEEN VASSAL LANE AND JUST SOUTH OF HURON AVE.

SECTION OF STREET BETWEEN BRATTLE STREET AND HURON AVENUE IS TOO WIDE OPEN, WHICH ENCOURAGES SPEEDING.

CONCERNED WITH LOSS OF ON-STREET PARKING BETWEEN VASSAL LANE AND JUST SOUTH OF HURON AVE. WOULD BE WILLING TO TRADE SOME ON-STREET PARKING SPACES IN REMAINING SECTION FOR OTHER IMPROVEMENTS - TREES, TRAFFIC CALMING, ETC.
- CYCLING ISSUES

DIFFICULT RIDE ON LAKEVIEW AVENUE BETWEEN HURON AVENUE AND FRESH POND PARKWAY. THERE ARE TOO MANY POTHOLES.

ONE-WAY STREETS MAKE CYCLING INEFFICIENT. CONSIDER TWO WAY CYCLING AND DESIGNATED BIKE LANES.

GLOBAL SUGGESTIONS

- MISCELLANEOUS SUGGESTIONS

CONSIDER PLANTINGS AND TREES. NEW GREENSPACES WOULD HAVE TO BE MAINTAINED BY NEIGHBORHOOD. #83, 87, AND 107 LAKEVIEW AVE ARE INTERESTED IN GARDENING.

CONSIDER OVERHEAD WIRE CALMING AND RELOCATE UNDERGROUND.

RAISED MEDIANS/ISLANDS ARE NOT PREFERRED.

HURON A PROJECT AREA
LAKEVIEW AVENUE

COMMENTS INCLUDED IN THIS FIGURE ARE FROM SURVEY RESPONSES AND COMMUNITY MEETING INPUT THROUGH 03.01.11

